SE	CRE	${f T}$

25X1

IDEA-0038-70 Copy___of_____

20 January 1970

MEMORANDUM FOR THE RECORD

SUBJECT: FY 1970 and 1971 Pressure Suit Requirements

REFERENCES: A. D/O/OSA Memo Idea-0073-70 dtd 7 Jan 1970

B. AMS/OSA Memo Idea-0034-70 dtd 8 Jan 1970

- 1. An inventory of spare parts has been accomplished at Detachment G to try and economize on S1010 PPA fabrication for the proposed replacement pilot schedule. At the present time there are available adequate vital components (gas bladder, link net, outer cover) at _______ to fabricate an additional full-pressure suit for the five (5) carbons at a cost of approximately \$35,000.
- 2. Since six (6) spare helmets. (three (3) at Detachment G and three (3) at were bought during FY-69, it will not be necessary to purchase any additional helmet assemblies. As pilots leave the program and are replaced, new helmet liners will be fabricated. This will provide a considerable saving in that a complete helmet assembly costs \$6,100.00 whereas the liner, alone, costs only \$500.00.

25X1

25X1

25X1

SECRET

 $\underline{\mathsf{SECRET}}$

25X1

IDEA-0038-70 Page 2

- 3. A schedule of reclamation and fabrication has been worked out; therefore, only two (2) completely new suits will be necessary. Rework of existing suits will fulfill the needs of the remaining additions to the project. fabricate a new suit costs \$16,000., including pattern work. To rework a first suit costs approximately \$12,000., including pattern work. To rework a second suit costs approximately \$6,000. A rework and fabrication chart is shown as Attachment #1.
- 4. Total cost for FY-1970 and 1971 full-pressure suits will be approximately \$150,000. The NRO has approved \$75,000. for FY-1970, and an additional \$77,000. will be required in FY-1971. These figures include preparing a second suit for the lat [well as two (2) S-1010 PPA's for all project pilots.

25X1

Chier, Aeromedical Staff Office of Special Activities

Attachment As stated above

25X1

AMS/OSA/ Distribution:

- 1 AMS/OSA w/att
- 2 D/O/OSA
- 3 Idea/O/OSA
- 4 SAS/O/OSA11
- 5 D/M/OSA**
- 6 D/SA
- 7 AMS/OSA Chrono "
- 8 RB/OSA w/o att

SECRET

ATTACHMENT # 1

 <u>Pilot</u>	Suit #	Action	Cost	
	427-1	New Suit	\$16,600	
	427-2	Rework from #406-1	\$4,000-6,000	
	428-1	Rework from #405	\$12,000	
	428-2	Rework from #406-2	\$4,000-6,000	
	429-1	Rework from #424-1	\$12,000	
	429-2	Rework from \$414	\$4,000-6,000	
	430-1	New Suit	\$16,600	
	430-2	Rework from #416	\$4,000-6,000	
	431-1	Rework from #404-2	\$12 ,000	
	431-2	Rework from #404-3	\$4,000-6,000	
	432-1	Rework from #408-1	\$12 ,000	
	432-2	Rework from #408-2	\$4,000-6,000	
		TOTAL	\$117,200	



ATTACHMENT # 1 Page 2

	\$117,200	
25X1	35,000	Cost to equip with a second suit
	152,200	
i.	75,000	Approved by NRO for FY-70 suits
	\$ 77,200	Needed to equipment new pilots in FY-71

		25/(1
	IDEA-0034-70 Copy_5 of_8	
	8 January 1970	-
	MEMORANDUM FOR THE RECORD	
	SUBJECT: FY-70 and 71 Pressure Suit Requirements	
	REFERENCE: D/O/OSA Memo, IDEA-0073-70 dtd 7 Jan 70	
	1. The following S-1010 PPA Full-Pressure suits and MC-3 partial pressure suits will be necessary in FY-70 and 71 to fulfill the criteria as outlined in the referenced Memorandum.	9. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1
	A. Two (2) S-1010 PPA's for Each pilot has two complete suit assemblies and one helmet.	25X1
	Cost breakdown	
	One suit assembly \$15,400.00 One helmet 6,100.00	
	Total cost for each pilot is \$36,900.00	25X1
	B. Two (2) S-1010 PPA's for the pilot to replace	25X1
	Total cost for the pilot is also \$36,900.0	₀ 25X1
*	SECRET	25X1

25X1

	•	SECRET IDEA-0034-70 Page 2	25X1
		<u>FY-71</u>	
25X1	·	A. Four (4) S-1010 PPA's for two (2) pilot replacements. Total cost \$73,800.00	
25X1		B. Two (2) S-1010 PPA's for two (2) pilot replacements. Total cost \$43,000.00	
		The Life Support Officer suggests the following be considered as a policy change and solicit your comments.	
25X1		In the past pilots have only been issued one full-pressure suit since it was anticipated that their commitment would not exceed three (3) years. Historically, this has not been the case and it is recommended, therefore, that all pilots in Category-I status be issued two (2) full-pressure suits. This change in philosophy will initially cost approximately \$30,000.00. As old suits become available with the completion of pilot obligations, hardware will be salvaged and backup suits provided for the remaining pilots at a somewhat reduced cost.	25X1
25X1		C. Two (2) MC-3 partial pressure suits for pilots. Total cost \$3,200.00 2. The NRO has approved \$75,000.00 for the purchase of pressure suits during FY-70. During FY-71 approximately \$120,000.00 will be necessary to adequately clothe the pilot replacements as discussed above.	
		3. Lead time necessary for fabrication of the S-1010 PPA in its entirety is four (4) months from the time of measurement. Lead time for fabrication of a partial pressure suit is two (2) months. Pressure-suit measurements should be accomplished as early as possible after final pilot selection to satisfy these lead times.	
		4. All U-2C flights for both pilots will be made below forty-five thousand (45,000) feet, therefore partial pressure suits will be unnecessary.	25X1 e,
		SECRET	25X1

Approved For Release 2003/11/25 : CIA-RDP75B00285R000300090028-0

	SECRE'T	0EV4
		25X1
	IDEA-0034-70	
	Page 3	
-	5. Indoctrination of replacement pilots in both the full and partial pressure suits will be accomplished utilizing the low-pressure chambers installed at These chamber flights are conducted to familiarize pilots with the pressure suit and to assure proper fit and mobility in	25X1
	the pressurized state. A considerable saving will be provided in performing these runs at since only the factory engineer and the Physiological Training Officer (PTO) have to travel. In the past, chamber flights have	25X1
	been given at the requiring travel of the Physician, PE man, pilot, PTO, and Factory Engineer to Buffalo, New York.	25X1
	Additionally, the Contractor cost to operate the chambers was averaging a pilot.	
	Chief, Aeromedical Staff Office of Special Activities	25X1
	Office of Special Activities	
•	C/AMS/OSA/ Distribution 1 - AMS/OSA 2 - D/O/OSA 3 - IDEA/O/OSA 4 - SAS/O/OSA 5 - D/SA 6 - D/M/OSA 7 - AMS/OSA Chrono 8 - RB/OSA	

25X1

25X1

Next 1 Page(s) In Document Exempt